

Government of Karnataka

Department of Public Works,

Office of the Executive Engineer, Special Division, Nazarbad, Mysore,

E - mail: eepwdspecialmysuru@gmail.com

Phone No. & Fax No. 0821 2492297

No:EEPWSDMAE-1;Building:safety:2021-22 1325-26

Date:28/10/21

To,

Secretary
Diocesan Education Society,
St. Joseph Educational Institutions,
Jayalakshmipuram, Mysore, 12

Sir,

Sub: Issuing Safety Certificate for the building of the St. Joseph's Educational Institute ,Rajeevnagar, Mysore -reg.

Ref: 1. Your letter dated: 16.08.2021

2. Asst. Executive Engineer, PWD No.2 Building Division, Mysore office letter No.589, dated:23/09/2021

With reference to the subject cited above the secretary has requested to for Safety Certificate for the school building of the St. Joseph's Educational Institute ,Rajeevnagar, Mysore city run by Secretary Diocesan Education Society, Mysore in your request of the ref (1) Asst. Executive Engineer, PWD No.2 Building Division, Mysore has submitted the details related to safety of the above school building in a prescribed format as above ref (2)

The building of the St. Joseph's Educational Institute ,Rajeevnagar, Mysore has been inspected jointly by the Asst. Executive Engineer, PWD No.2 Building Division, Mysore along with Secretary Diocesan Education Society, St. Joseph's Education Society, Jayalaxmipuram, Mysore on 19.08.2021 and 21.09.2021, it is observed that the building is in good condition.


Further, in regards with the safety of the building, the Asst. Executive Engineer, PWD No.2 Building Division, Mysore in his referred letter, necessary test such as Ultrasonic pulse Velocity Test, cracks, distress, dampness etc., are undertaken with **Karnataka Test House. Pvt. Ltd., Yashavanthapura, Bengaluru** on 12.03.2021. As per the report it is suggested to some rectification in the building and reported as the building is safety.

When verified with the all the documents and considering the certificate issued by **Karnataka Test House. Pvt. Ltd., Yashavanthapura, Bengaluru** that the building is safety structurally .and also found from the tests of the Technical team of the PWD, it is **structurally stable**. It is herby issued a Safety certificate for the period of 5 years from the period 2021-22 with the condition that to do suggested rectification in the building.

Yours sincerely
Sd/-
Executive Engineer
PWD,
Special Division, Mysore

Translated By

B.M. Lingaraj, M.A.(English)P.G. Diploma in Translation
Officer, RFUs of NTS-I,
Central Institute of Indian Languages
Manasaganagothri, Mysuru


True translation of the text /
entries in kannada language

Central Institute of Indian Language
MYSORE - 570 006